



Tips:

Pull pins all the way back and lock in place by putting a small allen wrench into hole. This holds the spring back and makes it much easier to put back together.

Put capacitor washers in one at a time and make sure that they are facing up (concave side down). Put the capacitor in to hold it in place before moving on to the next capacitor.