

AugerMap 2.1.1 Update Information

- Steering Y fine sliders now function properly
 - Steering X-Y sliders now have wider ranges
 - Improved area mode for 660 (79-170) systems, including area mode button added to TV dialog (for full area scan)
 - Create composites from dialog box bug fix
-

AugerMap 2.1.0 Update Information

- Elemental Survey Acquisitions
 - Line Scan Export as ASCII text
 - SEM Images Export as ASCII text
 - Elemental Region Images as ASCII text
 - Elemental Survey Regions as ASCII text
 - Image Registration for 660 systems
 - Line Scan Editing allows removal of regions
 - Line Scan Topographic Correction
 - Elemental Region Image Topographic Correction
 - Higher Resolution Thumbnails in Image Previews
 - More information in the information sidebar
-

AugerMap 2.0.3 Update Information

- Support for 20-327 Electron Gun Control
- Optional use of 21V on 79-170 systems for SED mapping
- Improved SED imaging on 79-170 systems
- Improved Auto-Video and Auto-Focus on 79-170 systems