

## www.rbdinstruments.com

## 18-085 Calibration Pots:

## **Analog Error Amp Board Adjustments**

**P1:** 2KV CAL

P3: .2MA on front panel meter with load on HV cable pin 6 to ground (3 KV with 30.1M = .1 MA, 1 KV with 10 M resistor

P4: Emission current limit set for shutdown at 300MA

**P5:** Emission Zero with beam at Zero

**P6:** Emission Zero with beam at 4 to 5 kV

P8: Filament Zero

**P10:** Filament gain 2.00 amps = 2.00 amps on front panel meter

**P11:** Filament current limit Set to 2.00 amps.

**P12:** 2.00 Amps with 6.7 volts on pin 113